29.16 METAL WORK (445)


29.16.1 Metal Work Paper 1 (445/1)





Answer all the questions in this section.

1	(a)	Name the most suitable extinguishing agent for putting out each of the following types of fires:		
		(i) petrol; (ii) gas;		
	•	(iii) wood;		
		(iv) electrical.	(2 marks)	
	(b)	Give two reasons for keeping an inventory in a workshop.	(2 marks)	
2	(a)	Give three reasons for marking out a work piece.		
	, ,	, .	(3 marks)	
	(b)	Illustrate the following sheet metal joints and state one application of eac (i) folded seam;	h :	
		(ii) knocked up joint.		
3	(a)	With reference to cutting external thread: (i) name two types of dies used:	(3 marks)	
		(ii) state two reasons for using cutting oil.	(3 marks)	
•	(b)	An M10 internal thread is to be cut in a mild steel plate. Given that the the pitch is 1.5mm, determine the size of the drill to be used	rread	
			(2 marks)	
4		Differentiate between the following:		
		(a) a rule and a ruler;		
		(b) bilateral and unilateral tolerance;		
		(c) trysquare and sliding bevel.	(3 marks)	
5	(a)	What is meant by the term heat treatment as applied to ferrous metals.	(1 magnitus	
			(1 mark)	
	(b)	Outline the procedure of heat treating a file ready for use.	(4 marks)	
6		Name each rivet shown in figure 1 and state one application of each.	(3 marks)	
7	State	four methods of identifying metals in a workshop.	(2 marks)	
8	Outli	ne the differences between:	<u> </u>	
		 (a) the oxygen set and the actylene set in oxy-acetylene equipment; (b) brazing and gas welding. 	(6 marks)	
9	Cina	two reasons for applying primer in painting process.	40	
.*		the reasons for apprying printer in painting process.	(2 marks)	
10.	Figur	e 2 shows orthographic view of a component.	•	
	Sketc	h in good proportion the isometric views of the component.	(4 marks)	




29.16

Figure 2

SECTION B (60 marks)

Answer question 11 and any other three questions from this section. Candidates are advised to spend not more than 25 minutes on question 11.

Figure 3 shows two views of a machined component drawn in first angle projection.



Draw full size, the following views:

- (a) sectional front elevation through P-P. Do not show the hidden details;
- (b) end elevation including hidden details.

(15 marks)

- 12 (a) Name three methods of testing the quality of gas-welded joints. (1½ marks)
 - (b) Sketch the correct flame for welding brass and outline the procedure of setting the flame. (5½ marks)
 - (c) Use labelled sketch to show an appropriate technique for gas welding thick plates and give three reasons for using the technique. (8 marks)
- (a) With the aid of a sketch, explain the term piping as applied to forging and state how it can be avoided. (3 marks)
 - (b) The end portion of a mild steel bar of cross-section 40 x 70mm is to be reduced to 20 x 70 by fullering. With the aid of sketches, outline the procedure of reducing the cross section naming the tools used in each step. (12 marks)
- 14 (a) Draw the following tables and show the components of each:
 - (i) cutting list;
 - (ii) bill of materials.

(7 marks)

- (b) Name and sketch **four** forms of metal supply and state one application of each. (8 marks)
- Outline the procedure of locating the centre of a round bar using the scribing block, surface plate and vee block. (3 marks)
 - (b) Figure 4 shows a micrometer screw gauge.

 Name the parts labeled A to F and state the function of each. (6 marks)




Figure 4

(c) Figure 5 shows different micrometer and vernier caliper readings. Determine the readings and show how each is obtained.

(6 marks)

